

Rancho Murieta Community Services District Security Department Memorandum

Date: 01/11/2023

To: Board of Directors From: Kelly Benitez

Subject: Safety Center Repairs – CIP# 23-19-03

RECOMMENDED ACTION

It is recommended that the Board approve the Bid from Gordian for repairs to the Safety Center for \$77,581 plus a 15% contingency for \$89,218. The District will appropriate the funds from the Security Replacement Reserve account.

BACKGROUND

This Safety Center was opened in July of 2006 as a community center for the Sacramento County Sheriff's Office, California Highway Patrol, and Security Personnel with the Community Service District (CSD). The Safety Center is a 1440 square-foot facility that includes a small kitchen and two restrooms, offices, and a locker room and is the hub for all CSD security personnel which includes the head of security.

The Safety Center is a community service center that in its current condition is not functional per our CSD standards. I would like to improve the functionality and inside space to attract more law enforcement personnel to visit the location and transform the inside of the Safety Center into an emergency operations center for CSD in the event of natural disasters or other types of emergencies.

Due to the age of the building, and improper sealing around the windows, there is extensive damage to the facility from leaks. The siding and flashing of the Safety Center are penetrated with dry rot. According to the SF GATE, of all the timber fungi, dry rot is one of the most dangerous, not just to the integrity of the building, but because of the underlying damp problem it represents. There are also several leaks in the Safety Center that have not been addressed over the past 16 years. This condition poses a real concern that mold may be discovered behind the panels. The windows on the Safety Center are single pane from the factory, many of which are failing and are not energy efficient.

The following repairs have been recommended:

- Replace siding affected with dry rot
- Replace 2' x 4' studs affected by dry rot
- Replace insulation affected by dry rot
- Install new dual-pane windows
- Install new trim around interior windows
- Install new gutters and trim
- Paint the exterior of the building
- As needed, consider replacing carpeting once the other repairs are complete

FINANCIAL IMPACT

CSD made inquiries regarding the company named Sourcewell. This government company helps buyers save time and money by combining the buying power of 50,000 government, education, and nonprofit organizations. Sourcewell holds hundreds of competitively solicited cooperative contracts ready for us by a public sector agency.

Sourcewell is authorized to establish competitively awarded cooperative purchasing contracts on behalf of itself and its participating agencies. Sourcewell follows the competitive contracting law process to solicit, evaluate, and award cooperative purchasing contracts for goods and services.

CSD registered with Sourcewell and received a detailed briefing regarding the company. The contracting company named Gordian was selected to provide CSD with a price proposal. Gordian provided a written proposal as well as an in-depth line-by-line review of the contract. The total amount of the proposal is \$77,581. Originally the District had budgeted \$68,000. We recommend approving the bid from Gordian as the cooperative purchasing process has already been completed. It is important to consider that there will likely be damage under the siding that cannot be seen until the work is started.



Work Order Signature Document

EZIQC Contract No.: CA-R1-GB01-123021-STA										
	X New Work Order	Modify an Ex	kisting Work Order							
Work Order Numb	er.: 112143.00	Work Order Date:	01/12/2023							
Work Order Title:	Rancho Murieta - Safety Center F	Rehab Window replace	ement and Siding							
Owner Name:	Rancho Murieta CSD	Contractor Name:	Staples Construction Company, Inc.							
Contact:	Michael Fritschi	Contact:	Mark Hodge							
Phone:	9163543700	Phone:	(916) 210 8130							
Sourcewell EZIQC Brief Work Order [ned as per the Final Detailed Scope of Victorial Contract No CA-R1-GB01-123021-ST/ Description: Head Window replacement and Siding, Dr	Α.								
Time of Perform	Estimated Completion Dat	te:								
Liquidated Dama	ages Will apply:	Will not apply:	X							
Work Order Firn	n Fixed Price: \$77,581.12									
Owner Purcha	ase Order Number:									
Approvals										
Rancho Murieta C	SD [Date Contracto	r Date							

Work Order Signature Document Page 1 of 1





Detailed Scope of Work

Amelia Wilder Mark Hodge To: From: Staples Construction Company Rancho Murieta CSD 6510 Lonetree Boulevard, Suite 101 15160 Jackson Road Rocklin, CA 95765 Rancho Murieta, CA 95682 (916) 210 8130 9163543700 **Date Printed:** January 12, 2023 Work Order Number: 112143.00 **Work Order Title:** Rancho Murieta - Safety Center Rehab Window replacement and Siding **Brief Scope:** Safety Center Rehab Window replacement and Siding, Dry rot, and Sheet Metal work **Preliminary** Revised X **Final** The following items detail the scope of work as discussed at the site. All requirements necessary to accomplish the items set forth below shall be considered part of this scope of work. See attached Subject to the terms and conditions of EZIQC Contract CA-R1-GB01-123021-STA. Contractor Date Rancho Murieta CSD

Date

Scope of Work Page 1 of 1

Contractor's Price Proposal - Summary

Date: January 12, 2023

Re: IQC Master Contract #: CA-R1-GB01-123021-STA

Work Order #:

112143.00

Owner PO #:

Title: Rancho Murieta - Safety Center Rehab Window replacement and Siding

Contractor: Staples Construction Company, Inc.

Proposal Value: \$77,581.12

Section - 01	\$2,714.53
Section - 01	φ2,7 14.33
Section - 06	\$19,581.54
Section - 07	\$20,969.03
Section - 08	\$24,022.99
Section - 09	\$10,293.03
Pronosal Total	\$77.581.12

ThisI total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding.

Contractor's Price Proposal - Detail

Date: January 12, 2023

Re: IQC Master Contract #: CA-R1-GB01-123021-STA

Work Order #:

112143.00

Owner PO #:

Title: Rancho Murieta - Safety Center Rehab Window replacement and Siding

Contractor: Staples Construction Company, Inc.

Proposal Value: \$77,581.12

	Sect.	Item	Mod.	UOM	Description	Line Total
Labor	Equip.	Material	(Excludes)			
Section	on - 01					
1	01 22 1	6 00 0002		EA Installatic	Reimbursable FeesReimbursable Fees will be paid to the contractor for eligible costs as directed by Owner. Insert the appropriate quantity to adjust the base cost to the actual Reimbursable Fee. If there are multiple Reimbursable Fees, list each one separately and add a comment in the "note" block to identify the Reimbursable Fee (e.g. sidewalk closure, road cut, various permits, extended warranty, expedited shipping costs, etc.). A copy of each receipt shall be submitted with the Price Proposal. Quantity Unit Price Factor Total	\$1,669.80
					1,518.00 ^ 1.00 ^ 1.1000	
					bond if required	
2	01 /4 1	9 00 0016		EA	40 CY Dumpster (4 Ton) "Construction Debris"Includes delivery of dumpster, rental cost, pick-up cost, hauling, and disposal fee. Non-hazardous material.	\$1,044.73
					Quantity Unit Price Factor Total	
				Installatio	n 1.00 x 614.98 x 1.6988 = 1,044.73	
Subto	otal for Se	ection - 0	1			\$2,714.53
Section	on - 06					
3	06 11 1	6 00 0061		SF	2" x 4" Wood Wall Framing At 16" On Center	\$1,964.66
				Installatio	Quantity Unit Price Factor Total 1.74 x 1.6988 = 1,330.16	
				Demolition Estimate	n 450.00 χ 0.83 χ 1.6988 = 634.50 d amount of framing to be redone.	
4	06 11 1	6 00 0061	0004	MOD	For >200 To 500, Add	\$229.34
				Installatio	Quantity Unit Price Factor Total 450.00 X 0.30 X 1.6988 = 229.34	
5	06 11 1	6 00 0158		LF	2" x 6" Wood Blocking To Wood	\$4,371.35
				Installatio	Quantity Unit Price Factor Total	, ,,
				Demolition Used for	n 280.00 $_{\rm X}$ 2.83 $_{\rm X}$ 1.6988 = 1,346.13 2.6 trim runner on front and back of building	
6	06 11 1	6 00 0209		LF	1" x 1" Cedar Light Framing, Trim And Furring	\$661.17
				Installatio	Quantity Unit Price Factor Total 140.00 x 1.91 x 1.6988 = 454.26	
				Demolition Used for	n 140.00 $_{\rm X}$ 0.87 $_{\rm X}$ 1.6988 = 206.91 wood trim on interior of windows	
7	06 11 1	6 00 0229		LF	1" x 4" Redwood Light Framing, Trim And Furring	\$872.84
				14.11.2	Quantity Unit Price Factor Total	
				Installatio	$^{\text{n}}$ $_{140.00}$ $^{\text{x}}$ $_{2.61}$ $^{\text{x}}$ $_{1.6988}$ $^{\text{=}}$ $_{620.74}$	
				Demolition Used for	n 140.00 $_{\rm X}$ 1.06 $_{\rm X}$ 1.6988 = 252.10 exterior trim of windows	

Contractor's Price Proposal - Detail Page 1 of 4

Contractor's Price Proposal - Detail Continues..

Work Order Number: 112143.00

Work Order Title: Rancho Murieta - Safety Center Rehab Window replacement and Siding

Secti	on - 06												
8	06 16	33	00 0014		SF	3/4" Inter	ior BC Plywoo	d Wall S	heathingApplied t	o wall stu	ıds.		\$6,650.80
					1		Quantity		Unit Price		Factor	Total	
					Installati	on	900.00	Х	3.28	Х	1.6988	5,014.86	
					Demoliti		900.00	Х	1.07	x	1.6988 =	1,635.94	
									ior. 3 damaged a	reas x 25	5'x12'.		
9	06 16	33	00 0014	0006	MOD	For Exter	rior CC Grade	Plywood	, Add				\$305.78
					Installati	on	Quantity	.,	Unit Price	.,	Factor =	Total 305.78	
							900.00	X	0.20	Х	1.6988	303.76	
10	06 16	33	00 0014	0011	MOD		ctive Replacen ew Plywood To			val Of Da	amaged Plywood A	And	\$4,525.60
						riung ive	Quantity	Size), A	Unit Price		Factor	Total	
					Installati	on	900.00	Х	2.96	X	1.6988 =	4,525.60	
Subte	otal for	Sec	ction - 06	}									\$19,581.54
Secti	on - 07												
11		16	00 0020		SF	3-1/2" Th	ick, Foil Faced	l, R-13 F	iberglass Flexible	Insulatio	on .		\$3,149.58
							Quantity		Unit Price		Factor	Total	,
					Installati	on	900.00	Х	1.64	x	1.6988	2,507.43	
					Demoliti	on	900.00	Х	0.42	x	1.6988 =	642.15	
12	07 26	13	00 0009		CLF	9" Wide S	Self Adhesive I	Butyl Sea	aling Tape				\$724.92
					1		Quantity		Unit Price		Factor	Total	
					Installati	on	1.80	Х	237.07	X	1.6988	724.92	
13	07 26	13	00 0010		CSF	Building \	Wrap (Tyvek)						\$1,162.13
					1		Quantity		Unit Price		Factor	Total	
					Installati	on	9.00	Х	76.01	X	1.6988	1,162.13	
14	07 41	13	00 0018		SF	0.0155", Panels	Corrugated Or	Ribbed,	Aluminum Expos	ed Faste	ner Metal Roof		\$6,497.91
			v		Installati	on	Quantity		Unit Price		Factor =	Total	
			Х				500.00	Х	4.71	Х	1.6988	4,000.67	
			Х		Demoliti		500.00	X Sanala v	2.94	X n the bee	1.6988 =	2,497.24 ler existing roofing	
						Material re		Jai leis X	40 111 110111 + 60 1	II lile bac	k to get gutter und	ler existing rooming	
15	07 46	29	00 0002		SF	5/8" T-11	1, Fine Grade	Siding, F	Paint Ready Applie	ed To Bla	ckboard / Stud		\$5,565.27
							Quantity		Unit Price		Factor	Total	
					Installati	on	900.00	Х	2.89	Х	1.6988	4,418.58	
					Demoliti		900.00	Х	0.75	x	1.6988 =	1,146.69	
							ent of damage						
16	07 62	19	00 0141		LF	>9" To 12		Thick, C	Clear Anodized Fi	nish, Alun			\$789.33
					Installati	on	Quantity	v	Unit Price	~	Factor	Total 789.33	
							32.00	X	14.52	Х	1.6988	709.55	
							over each nev						
17	07 71	23	00 0006		LF	5", 0.032	" Thick, K-Styl	e Alumin					\$1,926.44
					Installati	on	Quantity	х	Unit Price	x	Factor =	Total 1,926.44	
							100.00		11.34		1.6988 -		
40	07.7:		00.0000	0001				ıg. (porc	n over nang not ir	iciuaea).	60' across the ba	CK	<u> </u>
18	07 71	23	00 0006	0324	MOD	For Up To	o 100', Add		11.25		- ·	+	\$411.11
					Installati	on	Quantity	х	Unit Price	x	Factor =	Total 411.11	
							100.00		2.42		1.6988		

Contractor's Price Proposal - Detail

Contractor's Price Proposal - Detail Continues..

Work Order Number: 112143.00

Work Order Title: Rancho Murieta - Safety Center Rehab Window replacement and Siding

<u>Secti</u>	on - 07										
19	07 71	23 00 002	21	EA 5",	K-Style Aluminum G	utter End	d Cap				\$37.20
				Installation	Quantity		Unit Price		Factor =	Total	
				mətallatiUil	6.00	Х	3.65	Х	1.6988	37.20	
20	07 71	23 00 004	16	EA 3" I	Diameter, Round Alu	ıminum V	Vire Strainer				\$100.09
				Installation	Quantity	.,	Unit Price		Factor =	Total	
				Ilistallation	4.00	Х	14.73	Х	1.6988	100.09	
21	07 71	23 00 004	46 0333	MOD For	0.031" Thick, Add						\$21.20
				Installation	Quantity		Unit Price		Factor =	Total	
					4.00	Х	3.12	X	1.6988	21.20	
22	07 71	23 00 005	53	LF 2":	3", 0.019" Thick, R	ectangula	ar Aluminum Dow	nspout			\$437.07
		Quantity Installation 40.00	.,	Unit Price	.,	Factor =	Total 437.07				
					48.00	Х	5.36	Х	1.6988	437.07	
	07.74			12' x 4 spout							
23	07 71	23 00 005	53 0327	MOD Foi	Up To 100', Add		11-2-5 1		5	+ · ·	\$88.07
				Installation	Quantity	х	Unit Price	х	Factor =	Total 88.07	
	07.7:	00 00 00	-0 0000	1400 -	48.00		1.08		1.6988	30.0.	
24	07 71	23 00 005	53 0333	MOD Foi	0.031" Thick, Add		11-2-5 1		5	+ · ·	\$58.71
				Installation	Quantity 48.00	х	Unit Price 0.72	х	Factor = 1.6988	Total 58.71	
					48.00		0.72		1.0988		
Subt	otal for	Section -	07								\$20,969.03
Secti	on - 02										
Section - 08 25 08 51 13 00 0027		27	EA >10	\$20,565.33							
					minum Window (Tra		700)	9	,g		Ψ20,000.00
				Installation	Quantity	v	Unit Price	v	Factor =	Total 18,619.87	
					10.00 10.00	Х	1,096.06	X	1.6988		
				Demolition Used for 10 r	10.00 new dual pane low E	x Milgaar	114.52 d windows	Х	1.6988 =	1,945.47	
26	08 51	13 00 002	27 0073		Color Anodized Fin						\$1,076.36
					Quantity	,	Unit Price		Factor	Total	Ψ1,070.00
				Installation	•	x		х			
27	08 81	23 13 006			10.00		63.36		1.6988 =	1,076.36	
		23 13 000	67	SF 3/4	10.00 " Thick, Insulated Fa						\$1,905.29
		23 13 000	57	SF 3/4	" Thick, Insulated Fa						\$1,905.29
		23 13 000	57	SF 3/4			talled GlassTwo 1		vith 1/2" air space.	1,076.36	\$1,905.29
28	08 81	23 13 000		Installation	" Thick, Insulated Fa	actory Ins	talled GlassTwo 1 Unit Price	1/8" lites v	vith 1/2" air space. Factor	1,076.36 Total	
28	08 81			Installation MOD For	" Thick, Insulated Fa Quantity 121.38	actory Ins	talled GlassTwo 1 Unit Price	1/8" lites v	vith 1/2" air space. Factor	1,076.36 Total	\$1,905.29 \$476.01
28	08 81			Installation	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas	actory Ins	talled GlassTwo 1 Unit Price 9.24	1/8" lites v	vith 1/2" air space. Factor = 1.6988	1,076.36 Total 1,905.29	
		23 13 000	67 0028	Installation MOD For	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity	x ss, Add	talled GlassTwo 1 Unit Price 9.24 Unit Price	1/8" lites v	rith 1/2" air space. Factor 1.6988 =	1,076.36 Total 1,905.29	\$476.01
			67 0028	Installation MOD For	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity	x ss, Add	talled GlassTwo 1 Unit Price 9.24 Unit Price	1/8" lites v	rith 1/2" air space. Factor 1.6988 =	1,076.36 Total 1,905.29	\$476.01
——Subte		23 13 000	67 0028	Installation MOD For	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity	x ss, Add	talled GlassTwo 1 Unit Price 9.24 Unit Price	1/8" lites v	rith 1/2" air space. Factor 1.6988 =	1,076.36 Total 1,905.29	\$476.01
——Subte	otal for on - 09	23 13 000	08	Installation MOD For Installation	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity	x ss, Add x	Unit Price 9.24 Unit Price 2.31	x x	Factor 1.6988 = Factor 1.6988 =	1,076.36 Total 1,905.29	\$476.01
Subto	otal for on - 09	23 13 006 Section -	08	Installation MOD For Installation SF 1.0	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity 121.30	x ss, Add x	Unit Price 9.24 Unit Price 2.31	x x	Factor 1.6988 = Factor 1.6988 =	1,076.36 Total 1,905.29 Total 476.01	\$476.01 \$24,022.9
Subto	otal for on - 09	23 13 006 Section -	08	Installation MOD For Installation SF 1 C Installation	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity 121.30	x ss, Add x	Unit Price 9.24 Unit Price 2.31 Int Exterior Wood S Unit Price 0.88	x x Smooth S	Factor 1.6988 = Factor 1.6988	Total 1,905.29 Total 476.01 Total 2,959.99	\$476.01 \$24,022.9
Subto	otal for on - 09	23 13 006 Section -	08	Installation MOD For Installation SF 1 C Installation 140 LF x 12'	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity 121.30	x ss, Add x	Unit Price 9.24 Unit Price 2.31 Int Exterior Wood S Unit Price 0.88	x x Smooth S	Factor 1.6988 = Factor 1.6988	Total 1,905.29 Total 476.01 Total 2,959.99	\$476.01 \$24,022.9
Subto	otal for on - 09 09 91	23 13 006 Section -	08 08	Installation MOD For Installation SF 1 C Installation 140 LF x 12'	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity 121.30	x ss, Add x Vork, Pair x painted=	Unit Price 9.24 Unit Price 2.31 Int Exterior Wood S Unit Price 0.88 1680 + 300 SF on	x x x Smooth S x a damaged	rith 1/2" air space. Factor 1.6988 = Factor 1.6988 = iding Factor 1.6988 = d backside of buildir	Total 1,905.29 Total 476.01 Total 2,959.99	\$476.01 \$24,022.99
Subto Secti	otal for on - 09 09 91	23 13 000 Section -	08 08	Installation MOD For Installation SF 1 C Installation 140 LF x 12' SF 2 C	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity 121.30 Coat Primer, Brush W Quantity 1,980.00 on front of building properties of the primer	x ss, Add x Vork, Pair x vainted= f	Unit Price 9.24 Unit Price 2.31 Int Exterior Wood S Unit Price 0.88 1680 + 300 SF on It Exterior Wood S Unit Price	x x Smooth S x a damaged	rith 1/2" air space. Factor 1.6988 = Factor 1.6988 = iding Factor 1.6988 = d backside of buildir ding Factor =	1,076.36 Total 1,905.29 Total 476.01 Total 2,959.99	\$476.01 \$24,022.99 \$2,959.99
Subto Secti	otal for on - 09 09 91	23 13 000 Section -	08 08	Installation MOD For Installation SF 1 C Installation 140 LF x 12' SF 2 C Installation	"Thick, Insulated Fa Quantity 121.38 Low-E Coated Glas Quantity 121.30 Coat Primer, Brush W Quantity 1,980.00 on front of building properties of the primer	x ss, Add x Vork, Pair x vainted=	unit Price 2.31 Unit Price 2.31 Int Exterior Wood S Unit Price 0.88 1680 + 300 SF on It Exterior Wood S Unit Price 1.65	x x x Smooth S x damaged	Factor 1.6988 = Factor 1.6988 = Factor 1.6988 = iding Factor 1.6988 = d backside of buildir ding Factor 1.6988 =	Total 1,905.29 Total 476.01 Total 2,959.99 Total 5,549.98	\$476.01 \$24,022.99 \$2,959.99

Contractor's Price Proposal - Detail Page 3 of 4
1/12/2023

Contractor's Price Proposal - Detail Continues..

Work Order Number: 112143.00

Work Order Title: Rancho Murieta - Safety Center Rehab Window replacement and Siding

31	09 91	13 00 0484		oat Alkyd Anticorros cellaneous Metal St		l Primer, Brush/R	oller Worl	k, Paint Exterior		\$619.72
				Quantity		Unit Price		Factor	Total	
			Installation	320.00	X	1.14	X	1.6988	619.72	
			Used for pain	Used for painting of gutters and spouts						
32	09 91	13 00 0486		oats Alkyd Enamel, faces	Brush/Ro	oller Work, Paint I	Exterior M	liscellaneous Metal		\$1,163.34
				Quantity		Unit Price		Factor	Total	
			Installation	320.00	X	2.14	X	1.6988	1,163.34	
			Used for pain	ting of gutters and s	pouts					

Proposal Total \$77,581.12

This total represents the correct total for the proposal. Any discrepancy between line totals, sub-totals and the proposal total is due to rounding.



Subcontractor Listing

Date: January 12, 2023

Re: IQC Master Contract #: CA-R1-GB01-123021-STA

Work Order #: 112143.00

Owner PO #:

Title: Rancho Murieta - Safety Center Rehab Window replacement and Siding

Contractor: Staples Construction Company, Inc.

Proposal Value: \$77,581.12

Name of Contractor	Duties	Amount	%
No Subcontractors have been		\$0.00	0.00
selected for this Work Order			

Subcontractor Listing Page 1 of 1

Rancho Murieta Safety Center Rehab Window Replacement Detailed Scope of Work

- Remove and Replace 10 existing windows with new dual pane Low E windows
- Remove and replace damaged siding, framing, and plywood as needed
- Weatherproofing as needed for new window and siding installation
- Remove and replace interior and exterior trim with wood and paint to match existing for all windows.
- Remove and replace damaged insulation in walls as needed.
- Install Z metal flashing above trim on each new window.
- Paint gutters, downspouts and replaced siding and trim on exterior to match existing
- Replace damaged conduit coupling on back exterior of building.
- Gutter and down spouts on front and back of building. Porch cover on front of building not included.

Exclusions

- Mold abatement and remediation
- Permits and fees